#3

Q68219
10/052,395 Filed: 1/23/02
Masahiro MIYAMOTO, et al.
STRUCTURE FOR PREVENTING FAILURE
OF CONNECTOR
Page 1 of 8







FIG. 2




Q68219 10/052,395 Filed: 1/23/02 Masahiro MIYAMOTO, et al. STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Page 2 of 8




Q68219
10/052,395 Filed: 1/23/02
Masahiro MIYAMOTO, et al.
STRUCTURE FOR PREVENTING FAILURE
OF CONNECTOR
Page 3 of 8




Q68219 10/052,395 Filed: 1/23/02 Masahiro MIYAMOTO, et al. STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Page 4 of 8




Q68219
10/052,395 Filed: 1/23/02
Masahiro MIYAMOTO, et al.
STRUCTURE FOR PREVENTING FAILURE
OF CONNECTOR
Page 5 of 8



Q68219 10/052,395 Filed: 1/23/02 Masahiro MIYAMOTO, et al. STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Page 6 of 8



Q68219 10/052,395 Filed: 1/23/02 Masahiro MIYAMOTO, et al. STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Page 7 of 8



Q68219 10/052,395 Filed: 1/23/02 Masahiro MIYAMOTO, et al. STRUCTURE FOR PREVENTING FAILURE OF CONNECTOR Page 8 of 8

